

06/23/93

ABSTRACT

1 C_{60} and C_{70} carbon atom compounds are prepared
by evaporating graphite in an inert quenching gas. The
vapor of carbon is collected and is selectively extracted
with an organic non-polar solvent.

5

10

15

20

25

30

35